

Fault information

Annual vehicle inspection 24.3.2026 (rejected)

Parking brake roller brake test

Main inspection item	Braking equipment
Component	(1.4)(1.1.6) Parking brake
Location	Ei mitään
Fault	Difference between braking forces too large
Severity	Rejected

Frame

Main inspection item	Chassis and chassis attachments
Component	(6.1.1) Subframe
Location	Edessä
Fault	Rust damage
Severity	Rejected
Additional information	Ei saa hitsata

Transmission

Main inspection item	Other devices and equipment
Component	(6.1.7) Drag link dust boot
Location	Vasemmalla edessä ulompi
Fault	Damaged
Severity	Repair recommendation
Additional information	Korjattava 24.04.2026 mennessä.

Front axle

Main inspection item	Axles, wheels and suspension
Component	(5.3) Lower control arm bearing
Location	Vas. ja oik. takimmainen
Fault	Damaged
Severity	Rejected

Service brake

Main inspection item	Braking equipment
Component	(1.1.14) Brake disc
Location	Vasemmalla takana
Fault	Rusted
Severity	Rejected