

Vehicle:IOT-717

Customer:

Operator:

Date(D/M/Y):21/03/2026

WorkShop Info

Shop name:

Address:

Zip/Post code:

Contact:

Tel:

Fax:

Website:

E-mail:

Remark:

SKODA/VIN Identify/Auto Scan/

Total Number :61

VIN	TMBJH8NX1NY045460
01 Engine Electronics	Fault (9)
P2E5900	Active/Static
Cylinder 1 Alternative Fuel Misfire Detected	
P2E5B00	Active/Static
Cylinder 3 Alternative Fuel Misfire Detected	
P2E5C00	Active/Static
Cylinder 4 Alternative Fuel Misfire Detected	
P2E5A00	Active/Static
Cylinder 2 Alternative Fuel Misfire Detected	
P2E5800	Active/Static
Alternative Fuel Random/Multiple Cylinder Misfire Detected	
P030100	Passive/Abiogenesis
Cyl.1-Misfire Detected	
P030300	Passive/Abiogenesis

Cyl.3-Misfire Detected	
P036300	Passive/Abiogenesis
Misfire Detected - Fueling Disabled	
P030000	Passive/Abiogenesis
Random/Multiple Cylinder-Misfire Detected	
02 Transmission Electronics	Pass
03 Brake Electronics	Fault (1)
P056200	Passive/Abiogenesis
System Voltage-Low Voltage	
08 Climate Control Module	Pass
09 Electronic Central Electric	Pass
13 Distance Regulation	Fault (2)
U112300	Passive/Abiogenesis
Databus error value received	
U112200	Passive/Abiogenesis
Databus implausible message	
15 Airbag	Pass
17 Instrument Cluster	Fault (1)
U105400	Passive/Abiogenesis
Information electronics control module 1-No communication	
18 Auxiliary/Parking Heating	Pass
19 Data Bus OBD Interface	Pass
23 Brake Boost	Fault (2)
U140000	Passive/Abiogenesis
Function restriction-Function restriction due to low voltage	
U12DC00	Passive/Abiogenesis
ABS control module-received malfunction value	
2B Steering Column Lock	Pass
3C Lane Change Assistance	Pass
42 Driver's Door Electronics	Pass
44 Power Steering	Pass

4B Multi-Function Module	Pass
52 Passenger's Door Electronics	Pass
5F Information Electronics 1	Pass
6C Rear View Camera System	Pass
6D Rear Lid Electronics	Pass
75 Emergency Call Module And Communication Unit	Pass
76 Parking Aid	Pass
A5 Front Sensor For Drivers Assistant Systems	Pass
B7 Interface For Access/Start System	Pass
D6 Light Control Left 2	Pass
D7 Light Control Right 2	Pass
811E Burglary Protection Control Module FL	Pass
811F Burglary Protection Control Module FR	Pass
8120 Burglary Protection Control Module RL	Pass
8121 Burglary Protection Control Module RR	Pass